

2. **Exterior Lamp Post**

The lamp post shows signs of severe corrosion which may result in structural failure. It is possible that the severity of the corrosion may be due to the interaction between mixed metals



Lamp post, Image A.



Lamp post-detail, Image B.

Severe iron corrosion



Lamp post-detail of corrosion, Image C.