
CEPM24-00522 219 W. Venice Ave

HANNEMAN FAMILY TRUST

Roof tarp draped over building.




Tarp and roofing material on the roadway (rear) of property.



Tarp and trash / debris in alley.




Current condition of part of the roof.



Ceiling collapse within the structure.



Roof no longer protecting the structure.



Property has been posted.



• END OF SLIDE.